Approved For Release 2008/04/29 : CIA-RDP78B04558A001200010078-3

SECRET

OUT57466

1966 JAN 3 23 48Z

Declassification Review by NGA/DoD

P 032323Z
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2 AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 6195.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B-23 WAS USED IN MISSION 8064 FLOWN ON 30 DECEMBER 4 JAN 1966 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: MINUS DENSITY DOTS SPACE 1.6 INCHES APART AND 1.8 INCHES FROM THE OUTBOARD EDGE IN THE FIRST 900 FRAMES. FROM FRAME 901 TO 1200 THE DOTS ARE 1.1 INCHES FROM THE OUTBOARD EDGE OF THE FILM. TITLE INK SOLVENT IS SMEARED INTO THE FORMAT INTERMITTENTLY IN FRAMES 901 TO 1200. SHORT PLUS DENSITY LINES WITHIN 1.6 INCHES OF THE INBOARD EDGE ARE PRESENT IN FRAMES 996 TO 998. HEAT SPLICES ARE PRESENT BETWEEN FRAMES 031/032, 489/490, 2000/2001, 1739/1740 AND IN THE FORMAT OF FRAMES 485 AND 1729. A MANUFACTURING SPLICE IS PRESENT IN THE FORMAT OF FRAME 1573.

C. 9L SIDE: THERE ARE A SERIES OF MINUS DENSITY DOTS APPROXIMATELY 2 INCHES APART THAT ARE 1, 3, 7, 81/2, 83/4 INCHES

DISTRIBUTION

Cy No.	Office	Action
1/2	File	
	OS	
	ADMIN	
	SEC DR	
	P & PS	
	GSD	
	IPD	
	FD	
	PSD	
	PSD-ICB	
3/4/5	TID	
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	

SECRET

Approved For Release 2008/04/29 : CIA-RDP78B04558A001200010078-3

Approved For Release 2008/04/29 : CIA-RDP78B04558A001200010078-3

FROM THE OUTBOARD EDGE PARALLEL TO THE MAJOR AXIS OF THE MATERIAL. THESE DOTS ARE MOST NOTICEABLE IN THE FIRST QUARTER OF THE MISSION. A REPETITIVE EMULSION LIFT RECURS EACH 6 INCHES FROM FRAME 440 THROUGH 1559 AND AGAIN IN FRAMES 1800 THROUGH 1830. ISOLATED EMULSION LIFTS WERE ALSO DETECTED IN FRAMES 259, 280, 283, 297, 299, 302, 303, 304 AND 305. MANUFACTURING SPLICES ARE PRESENT BETWEEN FRAMES 821-822 AND IN FRAME 2652. HEAT SPLICES ARE PRESENT BETWEEN FRAMES 46/47, 142/143 AND IN FRAMES 183 AND 1559.

D. BOTH SIDES: BOTH SIDES CONTAIN ROLLER CHATTER TO VARYING DEGREES THROUGHOUT THE MISSION. THE RESULTS OF DENDRITIC STATIC IS APPARENT ALONG BOTH EDGES. THE MOST SIGNIFICANT DIGET IN THE FRAME COUNTER IS MARKED BY A SMALL PIECE OF PAPER OR TAPE THAT CONTAINS THE LETTER "W".

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES ON THIS MISSION. THE FRAMES WERE TITLED FROM 1 TO 2929.

3. POSITIVES:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING OF THE POSITIVES IS GOOD.

C. CLOUDS OBSCURE APPROXIMATELY 65 PERCENT OF THE PHOTOGRAPHY. GP-1.

S E C R E T

-END OF MESSAGE-

Approved For Release 2008/04/29 : CIA-RDP78B04558A001200010078-3